

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20181112-E181540  
**Report Reference** E181540-20111226  
**Issue Date** 2018-NOVEMBER-12

**Issued to:** SANYO ELECTRIC CO LTD OF PANASONIC GROUP  
15-2 NISHIKI-MINAMI-MACHI  
KAIZUKA-SHI  
OSAKA 597-0094 JAPAN

**This certificate confirms that  
representative samples of**

PHOTOVOLTAIC MODULES AND PANELS  
See Addendum Page

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:**

“Standard for Safety for Flat-Plate Photovoltaic Modules  
and Panels”, UL 1703 and “Flat-Plate Photovoltaic Modules  
and Panels”, ULC/ORD-C1703:2018

**Additional Information:**

See the UL Online Certifications Directory at  
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and  
covered under UL’s Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please  
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20181112-E181540  
**Report Reference** E181540-20111226  
**Issue Date** 2018-NOVEMBER-12

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

USL/CNL –

HIT-N195A followed by 07, 08, 09 or 10

HIT-N200A, HIT-N205A, HIT-N210A, HIT-N215A, HIT-N220A, HIT-N225A followed by 07, 08, 09, 10, 16, 17, 18 or 19

HIT-N230A, HIT-N235A followed by 16, 17, 18 or 19

HIT-N220SA, HIT-N225SA, HIT-N230SA, HIT-N235SA, HIT-N240SA, HIT-N245SA followed by 03, 04, 05 or 06.

HIT-N215SA, HIT-N220SA, HIT-N225SA, HIT-N230SA, HIT-N235SA followed by 07, 08, 09 or 10.

VBHN220SA, VBHN225SA, VBHN230SA, VBHN235SA, VBHN240SA, VBHN245SA followed by 03, 03B, 04, 04B, 05, 05B, 06, 06B, 11, 11B, 12 or 12B.

VBHN215SA, VBHN220SA, VBHN225SA, VBHN230SA, VBHN235SA followed by 07, 07B, 08, 08B, 09, 09B, 10 or 10B.

VBHN320SA, VBHN325SA, VBHN330SA, VBHN332SA, VBHN333SA, VBHN335SA, VBHN337SA, VBHN340SA, VBHN342SA, VBHN345SA followed by 15, 15B, 16, 16B, 17 or 18.

VBHNxxxKA# (xxx = 305 – 340: Where xxx are positive integers; # = 01, 02, 03 or 04)

VBHN320ZA, VBHN325ZA, VBHN330ZA followed by 01.

VBHNxxxZAyy (xxx = 305 – 325: Where xxx are positive integers; yy = 02 or 03 or 04)



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

